


2 Fundamentals of production-Tool Geometry

.1 Basic concepts

For the tool to be able to cut without great friction, we have to ensure:


1. A **clearance angle α** between tool flank and cut surface **to minimize friction.**
2. A **rake angle γ** between tool face and chip direction **to help for chip removal.**
3. A resulting **wedge angle β** between tool face and flank which **helps tool to penetrate through w.p.**




Note: Angle β must have an optimum value which ensures sufficient durability and strength of tool wedge and also sufficient tool conductivity.

.2 Main geometry of a single point tool

The main tool angles are determined and elaborated in the following drawings





Working drawing of a single point tool

Where:

- δ Cutting angle ($\delta = \alpha + \beta$)
- ϵ Nose angle
- χ Setting angle
- λ Main cutting edge inclination

.3 Choice of tool angles

The values of tool angles are chosen according to:



- The workpiece material
- The tool material
- The machining method
- Cutting conditions (v , s , t)
- Required Grad of accuracy (IT) and surface roughness (Ra).

Examples:



α : is influenced by tool material and amount of friction on tool flank. For hard material of wp and smaller $t \rightarrow \alpha \downarrow$. For HSS $\alpha = 5 - 8^\circ$ and for SC $\alpha = 4 - 6^\circ$.

β : The harder and stronger wp material $\rightarrow \beta \uparrow$. For soft materials (Al) $\rightarrow \beta = 25 - 45^\circ$ and for hard and brittle material (CI) $\rightarrow \beta = 75 - 85^\circ$

γ The rake angle is +ve for ductile and tough materials and -ve for hard and brittle.



λ influences direction of chip flow.



r (tool radius):

$r \uparrow \rightarrow$ tool strength $\uparrow \rightarrow Ra \downarrow$ but $r \uparrow \uparrow \rightarrow P_y \uparrow \uparrow \rightarrow$ vibrations $\rightarrow Ra \uparrow$

